



## How to Engrave Circles Inside a Vector Shape


1. Draw or import a vector graphic into the laser software.




2. Double click on the layer (top right hand corner of the PC screen) which corresponds to the vector shape in question.




3. The "Set Engrave options" window will open.



4. Press the “...” button.




5. The “Set Engrave Options(advanced)” window will open.



The default settings are:  
(unticked) Full Circle

If you want to engrave the inside of the shape with series of circles instead of a solid engraving, you can tick the “Full Circle” box (as shown in the image) and proceed to fill in the remaining settings as per your requirements for the radius of the circles, and the shape/distance between the circles.

This would produce the following type of effect;



**REMEMBER** to download your file to the laser machine again once any settings have been changed, for the settings to apply to the job you are running.

Please contact your supplier if you have any questions.